



**NUMBER:** 08-025-07 REV. A

**GROUP:** Electrical

**DATE:** December 7, 2007

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler LLC.*

**THIS BULLETIN SUPERSEDES TECHNICAL SERVICE BULLETIN 08-025-07, DATED OCTOBER 20, 2007, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **\*\*ASTERISKS\*\*** AND INCLUDE THE ADDITION OF NEW MODELS, SYMPTOMS/CONDITIONS, REPAIR PROCEDURE AND PARTS.**

**SUBJECT:**

DVD Software Update MYGIG Radio For Many Radio Improvements

**OVERVIEW:**

This bulletin involves updating the software for the MYGIG radio with the MYGIG radio software update DVD.

**MODELS:**

2007 - <b>**2008**</b>	(JS)	Sebring/Avenger
2007 - <b>**2008**</b>	(KA)	Nitro
2007 - <b>**2008**</b>	(JK)	Wrangler
<b>**2008</b>	(HB)	Durango <b>**</b>
<b>**2008</b>	(HG)	Aspen <b>**</b>
<b>**2008</b>	(LE)	300C/300C Touring (International Markets) <b>**</b>
<b>**2008</b>	(LX)	300/Magnum/Charger <b>**</b>
<b>**2008</b>	(MK)	Compass/Patriot <b>**</b>
<b>**2008</b>	(ND)	Dakota <b>**</b>
<b>**2008</b>	(RT)	Town & Country/Grand Caravan/Grand Voyager (U.S. and International Markets) <b>**</b>
<b>**2008</b>	(WH)	Grand Cherokee (International Markets) <b>**</b>
<b>**2008</b>	(WK)	Grand Cherokee <b>**</b>
<b>**2008</b>	(XH)	Commander (International Markets) <b>**</b>
<b>**2008</b>	(XK)	Commander <b>**</b>

**NOTE: This bulletin applies to the above listed vehicles equipped with a MYGIG radio (sales code RER, **\*\*REP\*\*** or REW) built before October 30, 2007 (MDH 1030XX).**



**Stick with the Specialists™**

**SYMPTOM/CONDITION:**

Vehicle operator may experience any of the following conditions:

- Radio displays “Module Failure”.
- Radio is stuck in “Demo Mode”.
- Disc stuck in radio.
- Unable to change language.
- \*\* Driver Speaker permanently muted after Adaptive Cruise Control Warning\*\*
- \*\*Guidance prompt does not remain in same state after key cycle (ON/OFF)\*\*
- \*\*Acceptance Screen never times out\*\*
- \*\*iPhone cannot connect \*\*
- \*\*Preset stations do not recognize driver 1 or driver 2 memory recalls \*\*
- \*\*Steering wheel radio switches not functional for volume control\*\*
- \*\*Displays hard to read when the radio is manually set to dim level #1 \*\*

**DIAGNOSIS:**

If the vehicle exhibits any of the above symptoms, perform the Repair Procedure.

**PARTS REQUIRED:**

Qty.	Part No.	Description
**1	68043349AB	<b>RER/REW</b> MYGIG Radio Software Update Disc**
**1	68044754AA	<b>REP</b> MYGIG Radio Software Update Disc**

**REPAIR PROCEDURE:**

1. Turn ignition to ACC. position.
2. Turn radio ON.
3. Insert software update DVD into radio.
4. Radio will read the disc and prompt user to perform software update.

**NOTE: Radio may take 1 - 2 minutes to prompt for software update.**

**NOTE: In the following step there are 2 portions to the software update. Radio will reset before and after each portion.**

5. If radio software is older than the update DVD software, i.e.; "Update from 8.044 to 9.041", select "Yes".

**NOTE: Once software update has begun, do not power off vehicle and do NOT touch the radio.**

6. Once software update is complete, radio will return to the normal user screen. Wait for radio to re-read DVD and prompts user to update software again. Software levels shown should now be identical, i.e.; Update from 9.041 to 9.041". Select "No" to return to user screen.
7. Eject software update DVD.
8. \*\*Turn ignition key off and wait 1 minute (allow CAN bus to go to sleep). \*\*
9. \*\*Turn ignition key to RUN. \*\*
10. \*\* Select "Menu" on radio.\*\*
11. \*\*Select "System Setup" on the display.\*\*
12. \*\*Select "System Information" on the display.\*\*
13. \*\*Confirm software display shows version "9.561 for RER/REW or 9.112 for REP" sales codes.\*\*

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

Labor Operation No:	Description	Amount
08-60-02-92	Update Software MYGIG Radio (B)	0.5 Hrs.

**FAILURE CODE:**

ZZ	Service Action
----	----------------