



NUMBER: 23-039-06

GROUP: Body

DATE: September 22, 2006

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.

THIS BULLETIN IS BEING PROVIDED IN ADVANCE. DO NOT ORDER PARTS OR PERFORM ANY ACTIONS RELATED TO THIS BULLETIN UNTIL SEPTEMBER 25, 2006.

SUBJECT:

Passenger Seat Manual Recliner Inoperative

OVERVIEW:

This bulletin involves installing a clip on the passenger seat recliner bell crank.

MODELS:

2006 - 2007	(WK)	Grand Cherokee
2006 - 2007	(XK)	Commander

SYMPTOM/CONDITION:

The passenger seat manual recliner is inoperative because the cable has detached from the recliner bell crank.

DIAGNOSIS:

This repair should be performed on all subject vehicles.

PARTS REQUIRED:

Qty.	Part No.	Description
1	68025170AA	Clip

REPAIR PROCEDURE:

1. Function passenger seat manual recliner handle to place seat back into forward most position if possible.
2. Adjust the passenger seat assembly to its most forward position to aid access to the rear of the seat side shield/trim panel.
3. Remove the passenger seat side shield/trim panel rear attaching screw.
4. Pull the side shield/trim panel slightly away from the seat to expose the plastic bell crank.
5. Ensure the recliner cable is properly positioned in the recliner bell crank.
6. Place clip, p/n 68025170AA into a ½ inch nut driver tool.
7. Position the clip over the rear edge of the recliner bell crank ensuring the clip is over both sides of the cable opening.



Stick with the Specialists™

8. Push the clip on to the bell crank, (Fig. 1). If the clip is not fully seated on the bell crank, tap the clip the rest of the way on with a small mallet.




Fig. 1 CLIP PROPERLY INSTALLED

- 1 - CLIP
- 2 - BELL CRANK

9. Align side shield/trim panel to proper position and install the attaching screw.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
23-13-50-92	Install Clip On Recliner Bell Crank	0.2 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------