



**NUMBER:** 24-020-05

**GROUP:** Heating & Air  
Conditioning

**DATE:** November 05, 2005

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.*

**SUBJECT:**

Manual Temperature Control - A/C Button LED May Illuminate Intermittently

**OVERVIEW:**

This bulletin involves the replacement of the Manual Temperature Control (MTC).

**MODELS:**

2006 (XK) Commander

**NOTE:** This bulletin applies to Commander vehicles built prior to November 01, 2005 (MDH 1101XX) and equipped with a Manual Temperature Control (sales code HAA).

**SYMPTOM/CONDITION:**

The customer may notice that the LED on the Manual Temperature Control - A/C On / Off button may illuminate (flash) intermittently. This condition may occur only during high vehicle speeds of approximately 112 Km/h (70 Mph) or greater. This condition may be accompanied by the intermittent cycling of the HVAC air recirculation door. An air rush or squeak-like sound may be heard as the recirculation door cycles.

**DIAGNOSIS:**

If the customer experiences the above condition, perform the Repair Procedure.

**PARTS REQUIRED:**

Qty.	Part No.	Description
1	55111009AL	Control, Manual Temperature

**REPAIR PROCEDURE:**

1. Replace the Manual Temperature Control. Refer to TechCONNECT for detailed repair instructions - Service Info tab / 24 - Heating & Air Conditioning / Controls / A/C Heater Control / Removal and Installation.

**POLICY:**

Reimbursable within the provisions of the warranty.



**TIME ALLOWANCE:**

<b>Labor Operation No:</b>	<b>Description</b>	<b>Amount</b>
24-50-10-94	Replace - Manual Temperature Control	0.4 Hrs.

**FAILURE CODE:**

ZZ	Service Action
----	----------------