



NUMBER: 26-002-08

GROUP: Miscellaneous

DATE: February 16, 2008

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler LLC.

SUBJECT:

Add Parking Brake Adjustment To The 30 Month, 30K Miles Or 50K Km Service Interval

MODELS:

2007 - 2008	(JK)	Wrangler
2007 - 2008	(JS41)	Avenger
2007 - 2008	(JS41)	Sebring
2008	(JS27)	Sebring Convertible
2007 - 2008	(KA)	Nitro
2005 - 2007	(KJ)	Liberty
2008	(KK)	Liberty
2005 - 2008	(LX)	300/Magnum/Charger
2007 - 2008	(LE)	300C/300 Touring (International Markets)
2007 - 2008	(MK)	Compass/Patriot
2007 - 2008	(PM)	Caliber
2005 - 2008	(PT)	PT Cruiser
2005 - 2007	(RG)	Chrysler Voyager (International Markets)
2005 - 2008	(WK)	Grand Cherokee
2005 - 2008	(WH)	Grand Cherokee (International Markets)
2006 - 2008	(XK)	Commander
2007 - 2008	(XH)	Commander (International Markets)

DISCUSSION:

The above listed vehicles now require that the parking brake adjustment procedure be added to the existing service interval of 30 months, 30K Miles Or 50K Km. This is only for vehicles equipped with four-wheel disc brakes.

Refer to the detailed procedures available in DealerCONNECT > TechCONNECT under: Service Info > Refer to 5 - Brakes/Parking Brake/Shoes - Adjustments

POLICY:

Information Only.